

ITB Q&A

Q: Do you have any spec's or information on the epoxy coating that is on that floor where the trench drain is being replaced? What is the expectations for patching that floor coating? Can I exclude that from my scope of work?

A: Patch the existing epoxy coating to an extent of 6 inches around the new trench drain with a self-leveling epoxy floor patch clear. Ensure the substrate is prepared per manufacturer instructions. Similar product can be found in this link: <https://www.revereproducts.com/self-leveling-epoxy-floor-patch-clear>

Q: D Also with the handrailing at the stairs. Is there a spec for that? Do you want painted handrails or should these be Stainless or Galvanized?

A: Handrailing should be replaced in like-kind and painted to match existing.